


Install Guide

2-587-TLW-BRO (8010 / 9008) SERIES



Caution: Ensure Housing or Remodel Driver is switched **OFF** before connecting LED trim. Failure to do so will cause **IMMEDIATE LED FAILURE**.

This LED device can only be connected to D4B 3 Housing, or with Dasal DRB 3 Remodel Driver with DP4-F-S-TLW plate

